


FLAT

INSTALLATION INSTRUCTIONS FOR SURFACE MOUNT

1. Make sure the total of L-shape mounting brackets has 12 each. 4 should be installed vertically and the rest should be installed horizontally as shown below.




2. Install the surface mount kit onto the ceiling.



3. Position the fixture parallel to the surface mount kit and insert the wires through the center opening.

4. Look for the side that has two exposed legs and slide in the fixture through the slot on vertically mounted L-shape brackets to secure.



5. Lock in the other end and secure 4 corners – two on the ends and one on each side.



6. Lastly, secure 4 more in the center to complete installation.



Contractor is responsible for adequately reinforcing ceilings to support luminaire weight. Utopia Lighting accepts no responsibility for inadequately reinforced ceilings. The information contained in this drawing is the sole property of Utopia Lighting. Any reproduction in part or whole is prohibited and warranty is voided.